

PX105678-EN RevB


## **INSTALLATION GUIDE**

FIBER EXPRESS ULTRA HD PATCH PANEL HOUSING - 4U/4U-23"/2U



#### **CABLE PREPARATION** C)

- 1.
- For correct fiber cable preparation, refer de figure 1 and figure 2. Mark outer armor (jacket) at distance"A" from end of the cable 2.
  - (if there is no outer armor (jacket), go to step 4) for distribution cable.
- Remove the outer cable armor (jacket) up to mark and, if necessary, clean surface. 3.
- Distribution cable: 4.
  - Mark outer armor of distribution cable at distance "B". 1.
    - Remove the outer cable armor (jacket) up to mark and, if necessary, clean surface 2.



### Figure 1: Cable length for Distribution cable




### Figure 2: Cable length for Loose Tube cable

-
0.37m (14.5in)

TRUNK CABLE (MPO)

### 0.61m (24in)


### **USING PRE-TERMINATED CASSETTES: MPO TRUNK CABLES** D)



# **INSTALLATION GUIDE**

FIBER *EXPRESS* ULTRA HD PATCH PANEL HOUSING - 4U/4U-23"/2U **E) USING TIGHT BUFFER : 900um TERMINATIONS** 





4U PATCH PANEL SHOWN AS REFERENCE


NOTE: Suggested management.

# **INSTALLATION GUIDE**

FIBER *EXPRESS* ULTRA HD PATCH PANEL HOUSING - 4U/4U-23"/2U **F) USING MPO TRUNK CABLES** 



4U PATCH PANEL SHOWN AS REFERENCE



4U PATCH PANEL SHOWN AS REFERENCE

PAGE 4 OF 4