



Rail

INSPECTION CERTIFICATE

according to DIN EN ISO/IEC 17020:2012

Holder of Inspection Certificate: **Belden Hirschmann Industries (Suzhou) Ltd.**

333 Yanhu Road, Huaqiao Town,
Kunshan City, Jiangsu Province
P.R. China

Inspection Certificate number: **BS101761C, V1.0**

Related Inspection Report: **BS101761G, V1.0**

Duration of inspection: 09.10.2023 - 25.01.2024

We herewith confirm that the
**Fire safety inspection of the
Dragonfly Industrial Wireless Access Point
(DAP847-XXXYXXXXXXXXX)**

with Hazard Level up to

HL 3

was inspected according to

DIN EN 45545-2:2020

The detailed inspection results, including the statement of compliance to the requirements of the inspection basis, are stated in the related inspection report. The listed hints, recommendations, and constraints in the related inspection report, as well as the safety related applicability conditions and environmental conditions of above-mentioned product, shall be considered.

TÜV SÜD Rail GmbH, Unit Rolling Stock

Release

Author

--	--