

# INSPECTION CERTIFICATE

according to DIN EN ISO/IEC 17020:2012

**Holder of inspection certificate:** **BELDEN SINGAPORE PRIVATE LIMITED**

151 Lorong Chuan, #05-01 New Tech Park,  
556741  
Singapore

**Inspection certificate number:** **BK105324C, V1.0**

**Related inspection report:** **BK105324T, V1.0**

**Duration of inspection:** 2025-06-30 - 2025-08-25

We herewith confirm that the

## **Dragonfly Industrial Wireless Access Point**

DAP849-RWAAZT6O6EHH, DAP849-USAAZT6O6EHH  
DAP849-MEAAZT6O6EHH, DAP849-JPAAZT6O6EHH  
DAP849-RWAAZT6O8EHH, DAP849-USAAZT6O8EHH  
DAP849-MEAAZT6O8EHH, DAP849-JPAAZT6O8EHH

with hazard level up to

**HL 3**

was inspected according to

**DIN EN 45545-2:2020, \*DIN EN 45545-2:2023**

\*) This standard is not part of the accreditation

The detailed inspection results, including the statement of compliance to the requirements of the inspection basis, are stated in the related inspection report. The listed hints, recommendations, and constraints in the related inspection report, as well as the safety related applicability conditions and environmental conditions of above-mentioned product, shall be considered.

TÜV SÜD Rail GmbH, Unit Rolling Stock

Released

Created

Released	Created

This document may not be reproduced, in full or in part, without prior written permission.